	8 7	6 5	4	3
D	REPLACEMENT KIT PART NUMBERS: • EN5038-01. • EN5038-02. • EN5038-03. • EN5038-04. • EN5038-05. • EN5038-06. • EN5038-07.	NOTE 7 & 8 NOTE 4 & 8	A7	
	 TOOLS NEEDED: NEEDLE NOSE PLIERS 5/16 WRENCH 3/8 WRENCH 		EEEE	
C				
В				Ô
	INSTRUCTIONS:			
	 TURN OFF (OPEN) AC INPUT CIRCUIT BREAKER (CB1), AND ALLOW INTERNAL VOLTAGES TO DISSIPATE. OPEN DOOR PANEL AND CAREFULLY REMOVE SAFETY SH USING A VOLTMETER AT A7 CAP BOARD TERMINALS TBS1 LOCATE A7 FILTER CAPACITOR PC BOARD ON INSIDE L 	IELDS. AND TBS2, VERIFY ALL POTENTAIL VOLTAGES IN THE CHARGER ARE A	AT "0".	ISO VIEW
A	BOARD. OTHERWISE, USE APPROPRIATE WRENCH TO LOC8.REPLACE (A7) WITH NEW (A7) CAPACITOR BOARD. LOC	Sers to gently pinch nylon stand-offs, and lift off $(A7)$ cap	UPDATED A7 BRKT MOU HARDWARE, INSTRUCTION S. PRESS TOOLS NEEDED	3/21/2023 KJB 3/24/2022 INTING DNS & CHK BY DATE: MS 3/24/2022 APP BY DATE: MCR 5/5/2022 UNLESS OTHERWISE SPECIFIED ANSI SYSTEM IPS (INCHESS-POUNDS & SECONDS)
	9. REINSTALL 10/32 HARDWARE ON $(A2)$ MOUNTING STUDS		ANY REPRODUCTION. PARTIAL OR AS A W DOCUMENT WITHOUT THE WRITTEN PER HINDLE POWER, INC IS STRICTLY PR	VHOLE OF THIS RMISSION OF
	8 7	6 5	4	3

